## OPTICARE Panoramic Angle Measurement Chart

## Instructions on how to use this Chart:

- 1. Place the frame so that the bridge is aligned with 0°. Ensure the frame is placed in a straight position.
- 2. The Panoramic Angle is where the lens ends, near the frame hinge. In this case, it is 20°.

